

High Tension

Excessive tension within the belt circuit should be avoided to maintain optimum running conditions. The following are known causes of high tension in Ladder-Track™ ladder belt applications:

- Belt damage preventing full articulation or side-flex
- Insufficient wear strip placement
- Seized or restricted bearing movement
- Excessive friction between belt and wear strip
- Excessive product loading